Facade membrane penetration

- Cut off Wigluv 20/40:
  leave approx. 4 cm on both sides
- Separate the narrow backing strip
  and affix in the corner
- Separate the wide backing strip
  and press on firmly
- Cut the corner at 45°

- Fold over
- Press on

- Repeat at each side of the penetration

4

How it should look:
- Square penetration sealed windtight using Wigluv 20/40.

5

How it should look:
- Penetration of open facade sealed windtight using Wigluv black

For closed facades:

Wigluv® 20/40

For open facades:

Wigluv® black 20/40

Joining window to facade membrane

- Pre-fold the corner using Wigluv 20/40
- Affix precisely in the window corner
- Repeat at all corners

Connect corners:
- Align Wigluv 20/40 in the corner
- Remove narrow backing strip
- Affix the narrow side to the window frame and press on

- Remove the wide backing strip
- Affix the wide side to the facade membrane and press on firmly

4

5

How it should look:
- Window sealed windtight using Wigluv 20/40

How it should look:
- The window next to a visible facade is sealed windtight with Wigluv black

For closed facades:

For open facades:

Wigluv ® 20/40

Wigluv ® black 20/40